

Stoke St Michael Parish Council Risk Assessment for Cleaning of the Village Lychgate

Description	Risk	Action/Notes
Lychgate	Falling roof tiles or flints – possible injury to pedestrians	Inspection of the Lychgate every year. Irregular checks by Councillor Warden when on site
Paths – Slips and Trips	<p>Paths cleared as part of the Maintenance Programme.</p> <p>Uneven surfaces to be reported to the Clerk</p>	<p>Footpaths gritted in icy conditions</p> <p>Leaves swept and cleared away in Autumn as surface is slippery when wet.</p>
Dog Fouling	Public and Warden	Educate the public through social media and signage

Approved:-